




Activating & Applying XpressPDF™ Loggers

- Step 1:
Fill out the origination detail.
- Step 2:
Press and Hold button on logger for two seconds until LED lights flash.
- Step 3:
Peel cover off glue dot on back of label, stick to front of paper.
- Step 4:
Place paper in protective sleeve; stick pouch to packaging.

Receiving XpressPDF™ Loggers

- ➡ If present on logger, press stop button
- ➡ Fill out receiving details on front
- ➡ Download PDF or CSV logger data

Emerson.com/Cargo
CargoTechSupport@Emerson.com
Toll Free: +1-877-998-7299



启动&使用温度记录仪

- 步骤1:
填写始发地信息。
- 步骤2:
紧按“Press & Hold”按钮2秒，直至LED灯闪烁。
- 步骤3:
撕掉温度记录仪背后的胶水贴片，粘到纸张正前方框内。
- 步骤4:
将纸张完整放入保护袋内。
撕除保护袋背后粘纸，将保护袋贴在货板上。

接收温度记录仪

- ➡ 如果部分记录仪有“STOP”按钮，则紧按此按钮
- ➡ 填写收货信息
- ➡ 读取温度记录仪所记录信息

Emerson.com/Cargo
邮箱: Cargochina@Emerson.com
热线电话: 400 887 9661 (周一至周五9:00-17:00)

Serial number
(序列号)

Part number & Duration
(编号及天数)

USB Interface
(USB 接口)

Tear Score
(撕线口)

Start/Mark
(启动/标记)

Active
(运行中)



User Guide

1. Keep Start button pressed for minimum 2 seconds to start
2. LED flashes 4 times, which indicates a successful starting
3. Keep button pressed one second until LED flashes to set a mark in the report

简易使用指导

1. 长按启动键至少2秒钟，运行灯亮开始记录
2. 启动按钮闪烁4次，表示启动成功
3. 按“标记”键直到LED灯闪，表示标记成功

Specifications

Recording Options: Single Use
Temperature Range: -30 — 70 °C
Temperature Accuracy: $\pm 0.5^{\circ}\text{C}$ for -30 — 70 °C
Data Storage: 25920 points
Logging interval: (5min for 90days; 10 min for 110 days)
Report Generation: Automatic PDF & CSV
Water proof rating: 1 meter for 1 hour, IP67
Shelf life: 15 months
Size: 58 mm * 36mm * 5.4 mm
Weight: 12g
Certifications: RCM, China RoHS

参数

记录次数: 单次使用
温度范围: -30 — 70 °C
温度准确性: -30 — 70 °C, $\pm 0.5^{\circ}\text{C}$
数据记录点: 25920 点
记录间隔5分钟/90天; 10分钟/110天
报告方式: PDF文档及CSV表格
防水性: 1米/1小时, IP67
货架期: 15个月
尺寸: 58毫米×36毫米×5.4毫米
重量: 12克
证书: RCM, China RoHS